

Production/Admin: 11/10/25  
Date  
Received/Costing  
Initial

Location

Initials of receiver (if shipment OK) Level 12

Part Number	Description	Quantity Ordered	Quantity Received	Quantity Returned	Quantity Short	Comments

Discrepancies

Batch No: M119384  
Part P/O: 15216  
Release Note Attached: ☒ Yes  
Waybill Attached: ☒ Yes  
Shipment Complete: ☒ Yes  
QC6 Inspection: ☒ Yes  
Work Order: ☒ Yes

Date: 11/10/25  
Supplier: QAMPI  
Packing Slip: ☒ Yes  
Invoice: ☒ Yes  
Receipt: ☒ Yes  
Cash: ☒ Yes  
Cr: ☒ Yes

## Receiving Report

N/A  
N/A  
N/A  
N/A  
N/A

All amounts are calculated in domestic currency.

All Item ID/GL/WOs	All Rec. Employees	All Currencies
--------------------	--------------------	----------------

Grouped by Vendor ID

<b>VendorID\Vendor Name</b>	<b>VC-CAM002</b>	<b>Campi Steel</b>						
PO15216	1	M5052H32S.040	sf	10/25/2011	10/26/2011	96.0000	\$1.45	0.0000
								0
CAD	No	5052-H32.040 Sheet	sf	96.0000	DESJ02		\$139.65	0.0000
		119384						
<b>Total Received Quantity:</b>								96.0000

<b>Total Received Quantity:</b>	96.0000
<b>Total Qty to Inspect (PO U/M):</b>	0.0000
<b>Total Reject Quantity:</b>	0.0000
<b>Total Receipt Value:</b>	\$139.65
<b>Total Balance Due Quantity:</b>	0.0000



**DART aerospace**  
 Dart Aerospace Ltd.  
 1270 Aberdeen Street  
 Hawkesbury, ON K6A 1K7  
 Tel: 613 632 9577  
 Fax: 613 632 1053

**PURCHASE ORDER**  
 Purchase Order ID PO15216  
 Purchase Order Date 10/20/11  
 PO Print Date 10/20/11  
 Page Number 1 of 1

VC-CAM002

Order From :  
 CAMPI STEEL  
 935 BOUL. DU HAVRE  
 VALLEYFIELD, QC J6S 5L1  
 CA

Buyer

Requisition Nbr  
 Tax Resale Nbr  
 Terms  
 Currency

Chantal Lavoie  
 10127-2607  
 Net 30  
 CAD  
 Destination-Collect

Contact Name  
 Vendor Phone  
 Vendor Fax  
 Vendor Account Nbr

800 667 4248  
 450 377 5696

Ship To :  
 DART AEROSPACE LTD  
 1270 ABERDEEN  
 HAWKESBURY, ON K6A 1K7  
 CANADA

**FAKED**  
 10/20/11

Line Nbr	Reference	Description/ Mfg ID	Reg Date/ Taxable	Reg Qty/ Unit of Measure	Ship Method	Unit Price	Extended Price
1	M5052H32S.040	5052-H32 .040 Sheet	10/25/11	96.00 Yours ppd		\$1.4547	\$139.65

Special Inst: MATERIAL: 5052H32 ALUMINUM SHEET  
 AS PER QQ-A-250/8 OR AMS-QQ-A-250/8  
 OR AMS 4016  
 OR ASTM B209  
 10/25/11

PO Total:

\$139.65

**MATERIAL CERTIFICATION**  
**REQ'D UPON DELIVERY**

No substitution or deviation without  
 consent.  
 Certificate of Conformity or Material  
 Certification required when applicable

Change Nbr: 1  
 Change Date: 10/20/11

ORIGINAL

INSPECTION CERTIFICATE

No 315683/03 Date 09-11-23

EN 10204/3.1

Release Order Number R131811

L/C RRR1-529515

8318679  
DIXIE

GOODS DESCRIPTION				
Alloy	5052	Batch No	315683/03	Length
		Thickness	1,020	Width
		Dimensions [mm]	1219,20	L
Temper	H32			

CHEMICAL ANALYSIS									
Heat/Net No	921173	Fe	0.302	Si	0.139	Cu	0.016	Mg	2.455
		Mn	0.088	Cr	0.161	Ti	0.015	Zn	0.031
Other									

MECHANICAL AND OTHER PROPERTIES					
Slab/Coil No	9211731	Rm	238	R <sub>p0.2</sub>	194
		[MPa]		[MPa]	
		A <sub>50</sub>	12	(%)	
Other		Hardness		[HB, V]	

WE HEREBY CERTIFY THAT THE GOODS COMPLY WITH AMS-QQ-A-250/8A, ASTM B209, ANSI-H35.2  
IN ALL RESPECTS

U. Lucas T/S, 001647  
LABORATORY MANAGER

TRANSPORT and STORAGE CONDITIONS OF ALUMINIUM STRIPS AND SHEETS BY CUSTOMER  
Strips (sheets) should be transported by covered, dry and clean means of transport preventing corrosion, protecting it from mechanical damage, handling and harmful environmental factors.  
Strips (sheets) should be stored in covered, dry and clean rooms protecting them from handling and action of active chemicals. Prevention of coil edge sagging mechanism/ damage should be taken into special account. Bending, face damage can cause difficulties in unwinding process.  
The storage temperature room should be stable. Changes of the temperature in stock cause that air moisture is condensed on the strip surface, in consequence of sagging activity, between coils, generating inside and outside corrosion.  
Deregulation of above mentioned transport and storage conditions obligates from responsibility for material quality.

315683-03